# Corrigendum - V

## Tender No.: WTL/CT/MPLS/17-18/002 dated 21.04.2017

| Sl. No. | Section | Clause No. | Page No. | Present Entry | Replace with |
|---|---|---|---|---|---|
| 1. | G | | 26 | At central site the routers provided should be in HA mode to ensure maximum uptime. Also link at SDC site should be provided on underground media. | Link at SDC site should be provided on underground media. |
| 2. | P | | 41 | Other than above reports following reports shall be submitted - **Interface Availability, Interface Traffic statistics, Interface Response time monitoring, Interface errors, NMS-MIS reports / MRTG Report & Real time and Historical web based reports** and **web based monitoring through portal** | Other than above reports following reports shall be submitted - **Interface Availability, Interface Traffic statistics, Interface Response time monitoring, Interface errors, NMS-MIS reports / MRTG Report & Real time and Historical web based reports** and **web based monitoring through portal. Bidder will provided above mentioned reports as per requirement basis from Service provider own system.** |